

Active Errata List

- No Active Erratas in Latest Version of Bootloader.

Errata History

Bootloader Version	Errata List
1.1.1	1, 2, 3, 4, 5, 6, 7
1.2.0	All known troubles fixed

Errata Descriptions

1. ISP Command Read Data

In response to an ISP Command Read Data, the bootloader sends the last data frame with stuffing bytes (FFh) to keep 16-byte frame length.

Workaround

ISP software host application should ignore these stuffing data bytes.

2. SBV and BSB Protection in ISP Mode

SBV and BSB modification are possible regardless of security level settings (SSB).

Workaround

The ISP software host application should read the SSB value before allowing any SBV and BSB modification according to the SSB setting.

3. Fuse Bits (X2, BLJB and OSCB for IC2 Product) Protection in ISP Mode

Any fuse bits modification (read or write access) are possible regardless of security level settings (SSB).

Workaround

The ISP software host application should read the SSB value before allowing any fuse bits modification according to the SSB setting.

4. Unexpected Response from Bootloader When a Security Level Change is Requested from the ISP Software Host Application

If the security levels are set to 1 or 2, the bootloader returns “.” instead of “P” over the serial line when the ISP software host application requests lower security level settings. However, the bootloader does not process the request and the current security level is not modified.

Workaround

The ISP software host application should not request inconsistent security level modification. If not possible, it should ignore the bootloader response.



80C51 Microcontrollers

T89C51RC2 T89C51RB2 T89C51IC2 Bootloader

Errata Sheet



5. **Bad Interrupt Handling During an API Call**

Interrupts are not disabled during all API process. This may cause interaction with software application interrupts using MOVX instruction.

API functions always enable interrupts (set EA) before exiting. This may cause trouble if API is called from a software program section requiring interrupts to be disabled.

Workaround

The software application should save and disable EA before an API call. On API return, the software application should restore EA setting.

6. **Program Data Byte and Data Page API Return Value**

The PROGRAM DATA BYTE API and DATA PAGE API returns "01h" instead of "00" into the accumulator, when Flash write process passed.

Workaround

The software application should take into account that return value is "01" with 1.1.1 bootloader version.

7. **No Further ISP is Possible When OSCB Fuse Bit Set and 32 kHz are Connected to XTAL2 for T89C51IC2 Product Only**

When OSCB fuse bit is set (written with 0), and XTAL2A/B pins connected to a 32 kHz oscillator, no serial ISP is possible.

Workaround

Connect at least a 1.8432 MHz signal to XTAL2A pin.



Atmel Headquarters

Corporate Headquarters

2325 Orchard Parkway
San Jose, CA 95131
TEL 1(408) 441-0311
FAX 1(408) 487-2600

Europe

Atmel Sarl
Route des Arsenaux 41
Case Postale 80
CH-1705 Fribourg
Switzerland
TEL (41) 26-426-5555
FAX (41) 26-426-5500

Asia

Room 1219
Chinachem Golden Plaza
77 Mody Road Tsimhatsui
East Kowloon
Hong Kong
TEL (852) 2721-9778
FAX (852) 2722-1369

Japan

9F, Tonetsu Shinkawa Bldg.
1-24-8 Shinkawa
Chuo-ku, Tokyo 104-0033
Japan
TEL (81) 3-3523-3551
FAX (81) 3-3523-7581

Atmel Operations

Memory

2325 Orchard Parkway
San Jose, CA 95131
TEL 1(408) 441-0311
FAX 1(408) 436-4314

Microcontrollers

2325 Orchard Parkway
San Jose, CA 95131
TEL 1(408) 441-0311
FAX 1(408) 436-4314

La Chantrerie
BP 70602
44306 Nantes Cedex 3, France
TEL (33) 2-40-18-18-18
FAX (33) 2-40-18-19-60

ASIC/ASSP/Smart Cards

Zone Industrielle
13106 Rousset Cedex, France
TEL (33) 4-42-53-60-00
FAX (33) 4-42-53-60-01

1150 East Cheyenne Mtn. Blvd.
Colorado Springs, CO 80906
TEL 1(719) 576-3300
FAX 1(719) 540-1759

Scottish Enterprise Technology Park
Maxwell Building
East Kilbride G75 0QR, Scotland
TEL (44) 1355-803-000
FAX (44) 1355-242-743

RF/Automotive

Theresienstrasse 2
Postfach 3535
74025 Heilbronn, Germany
TEL (49) 71-31-67-0
FAX (49) 71-31-67-2340

1150 East Cheyenne Mtn. Blvd.
Colorado Springs, CO 80906
TEL 1(719) 576-3300
FAX 1(719) 540-1759

Biometrics/Imaging/Hi-Rel MPU/ High Speed Converters/RF Data- com

Avenue de Rochepleine
BP 123
38521 Saint-Egreve Cedex, France
TEL (33) 4-76-58-30-00
FAX (33) 4-76-58-34-80

e-mail

literature@atmel.com

Web Site

<http://www.atmel.com>

© Atmel Corporation 2002.

Atmel Corporation makes no warranty for the use of its products, other than those expressly contained in the Company's standard warranty which is detailed in Atmel's Terms and Conditions located on the Company's web site. The Company assumes no responsibility for any errors which may appear in this document, reserves the right to change devices or specifications detailed herein at any time without notice, and does not make any commitment to update the information contained herein. No licenses to patents or other intellectual property of Atmel are granted by the Company in connection with the sale of Atmel products, expressly or by implication. Atmel's products are not authorized for use as critical components in life support devices or systems.

ATMEL® is a registered trademark of Atmel.

Other terms and product names may be the trademarks of others.



Printed on recycled paper.