1. Active AT89C51SND2C Errata List

- SPI Controller Bad Transfer in Slave Mode with CPHA = 0
- C51 Core Bad Exit of Power-down in X2 Mode
- MP3 Decoder Bad Cut Frequency of Bass, Medium, Treble Control
- MP3 Decoder Bass Boost Effect
- MP3 Decoder Sampling Frequency Report in MP3 Status Register
- MP3 Decoder Extra Power Consumption after Reset
- Modulation

2. AT89C51SND2C Errata History

Lot Number	Errata List
All lots	1, 2, 3, 4, 5, 6, 7

3. AT89C51SND2C Errata Description

1. SPI Controller – Bad Transfer in Slave Mode with CPHA = 0

SPI controller used in slave mode with CPHA = 0 leads to erratic data reception and transmission.

Workaround

Use slave mode only with CPHA = 1.

2. C51 Core – Bad Exit of Power-down in X2 Mode

When exiting Power-down mode by interrupt while CPU is in X2 mode, it leads to bad execution of first instruction executed when CPU restarts.

Workaround

Put the CPU in X1 mode just before entering power-down mode.

3. MP3 Decoder – Bad Cut Frequency of Bass, Medium, Treble Control

The cut frequency of bass control is 300 Hz instead of 750 Hz and cut frequency of treble control is 2 kHz instead of 3.3 kHz.

Workaround

No workaround available.

4. MP3 Decoder – Bass Boost Effect

Enabling the built-in bass boost effect with some MP3 song leads to sound distorsion.

Workaround

Use the equalizer bass band control instead of bass boost control.



MP3 Microcontrollers

AT89C51SND2C

Errata Sheet







5. MP3 Decoder – Sampling Frequency Report in MP3 Status Register

MPFS1:0 bits in MP3STA register are always set to 1 and do not report Sampling Frequency value.

- MP3STA register reset value = 0000 0111b
- MP3STA1 register reset value = 0001 0111b

Workaround

No workaround available.

6. MP3 Decoder – Extra Power Consumption after Reset

Under certain power-up conditions, MP3 decoder may not be well reset leading to an extra power consumption. This extra consumption diseappears after playing one MP3 song.

Workaround

The software workaround consists in enabling and disabling the MP3 macrocell while PLL is running. This starts internal decoder reset process and remove the extra power consumption.

Implemented in latest firmware packages.

7. Modulation

Approximately 1 KHz, for pure sinus wave input, depending on the volume band, some modulation may appear for input signal levels above -9dB.

Workaround

Use input signal level lower than -9dB.

4. Active USB Bootloader Errata List

No Active Errata

5. USB Bootloader Errata History

Version Number	Errata List
V1.6.2	No Active Errata

6. USB Bootloader Errata Description

1. Boot Process - Marginal SBV Value

When Bootloader is called from user's application with SBV = F0h, the bootloader is never executed and execution enters an infinite loop.

Workaround

Always set SBV value to FFh instead of F0h.



Atmel Corporation

2325 Orchard Parkway San Jose, CA 95131, USA Tel: 1(408) 441-0311 Fax: 1(408) 487-2600

Regional Headquarters

Europe

Atmel Sarl Route des Arsenaux 41 Case Postale 80 CH-1705 Fribourg Switzerland Tel: (41) 26-426-5555 Fax: (41) 26-426-5500

Asia

Room 1219 Chinachem Golden Plaza 77 Mody Road Tsimshatsui East Kowloon Hong Kong Tel: (852) 2721-9778 Fax: (852) 2722-1369

Japan

9F, Tonetsu Shinkawa Bldg. 1-24-8 Shinkawa Chuo-ku, Tokyo 104-0033 Japan Tel: (81) 3-3523-3551 Fax: (81) 3-3523-7581

Atmel Operations

Memory

2325 Orchard Parkway San Jose, CA 95131, USA Tel: 1(408) 441-0311 Fax: 1(408) 436-4314

Microcontrollers

2325 Orchard Parkway San Jose, CA 95131, USA Tel: 1(408) 441-0311 Fax: 1(408) 436-4314

La Chantrerie BP 70602 44306 Nantes Cedex 3, France Tel: (33) 2-40-18-18-18 Fax: (33) 2-40-18-19-60

ASIC/ASSP/Smart Cards

Zone Industrielle 13106 Rousset Cedex, France Tel: (33) 4-42-53-60-00 Fax: (33) 4-42-53-60-01

1150 East Cheyenne Mtn. Blvd. Colorado Springs, CO 80906, USA Tel: 1(719) 576-3300 Fax: 1(719) 540-1759

Scottish Enterprise Technology Park Maxwell Building East Kilbride G75 0QR, Scotland Tel: (44) 1355-803-000 Fax: (44) 1355-242-743

RF/Automotive

Theresienstrasse 2 Postfach 3535 74025 Heilbronn, Germany Tel: (49) 71-31-67-0 Fax: (49) 71-31-67-2340

1150 East Cheyenne Mtn. Blvd. Colorado Springs, CO 80906, USA Tel: 1(719) 576-3300 Fax: 1(719) 540-1759

Biometrics/Imaging/Hi-Rel MPU/ High Speed Converters/RF Datacom

Avenue de Rochepleine BP 123 38521 Saint-Egreve Cedex, France Tel: (33) 4-76-58-30-00 Fax: (33) 4-76-58-34-80

Literature Requests www.atmel.com/literature

Disclaimer: The information in this document is provided in connection with Atmel products. No license, express or implied, by estoppel or otherwise, to any intellectual property right is granted by this document or in connection with the sale of Atmel products. EXCEPT AS SET FORTH IN ATMEL'S TERMS AND CONDI-TIONS OF SALE LOCATED ON ATMEL'S WEB SITE, ATMEL ASSUMES NO LIABILITY WHATSOEVER AND DISCLAIMS ANY EXPRESS, IMPLIED OR STATUTORY WARRANTY RELATING TO ITS PRODUCTS INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTY OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, OR NON-INFRINGEMENT. IN NO EVENT SHALL ATMEL BE LIABLE FOR ANY DIRECT, INDIRECT, CONSEQUENTIAL, PUNITIVE, SPECIAL OR INCIDEN-TAL DAMAGES (INCLUDING, WITHOUT LIMITATION, DAMAGES FOR LOSS OF PROFITS, BUSINESS INTERRUPTION, OR LOSS OF INFORMATION) ARISING OUT OF THE USE OR INABILITY TO USE THIS DOCUMENT, EVEN IF ATMEL HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES. Atmel makes no representations or warranties with respect to the accuracy or completeness of the contents of this document and reserves the right to make changes to specifications and product descriptions at any time without notice. Atmel does not make any commitment to update the information contained herein. Atmel's products are not intended, authorized, or warranted for use as components in applications intended to support or sustain life.

© Atmel Corporation 2005. All rights reserved. Atmel[®], logo and combinations thereof, are registered trademarks, and Everywhere You AreSM [insert any additional, applicable Atmel marks here] are the trademarks of Atmel Corporation or its subsidiaries. Other terms and product names may be trademarks of others.



4414A-MP3-02/05